Confined Space Inventory-City of New London July 10, 2012

Space #	Location	Structure #	Type/Size	Access	Primary Hazard	Other	Entry Classification
Hatten Park	Sanitary Stadium Holding Tank	Photo(s) #1	Underground tank	Top	Air Quality	Fall/engulfment	**Permit-Required**
Hatten Park	Kunkle Building Sump Pump Pit	Photo(s) #2	Manhole	Top	Air Quality	Fall/Lockout	**Permit-Required**
Hatten Park	Kunkle Basement Pool Pit	Photo(s) #3	Concrete Vault	Top	Air Quality	Fall/Access	**Permit-Required**
New London Aquatic Center	Chemical Room Pump Pit	Photo(s) #4	Concrete open top	Top	Lockout/Tagout	Fall	**Re-classified Non-Permit** for routine maintenance only so long as **no** hazardous atmosphere introduced (e.g., painting, welding, etc.) and equipment can be isolated without entry and air is verified safe for entry - otherwise **Permit-Required**
New London Aquatic Center	Chemical Room Filter Pit	Photo(s) #5	Concrete open top	Top	Lockout/Tagout	Fall	**Re-classified Non-Permit** for routine maintenance only so long as **no** hazardous atmosphere introduced (e.g., painting, welding, etc.) and equipment can be isolated and drained without entry and air is verified safe for entry-otherwise **Permit- Required**
New London Aquatic Center	Chemical Room Surge Tank	Photo(s) #6	Concrete	Top	Air Quality and Engulfment	Fall	**Permit-Required**
New London Aquatic Center	Chemical Room Sump Pit	Photo(s) #7	Manhole	Top	Air Quality	Fall	**Permit-Required**
New London Aquatic Center	Empty Swimming Pool	NO PHOTO	Concrete open top	Top	Fall		**Non-permit required** so long as no hazardous atmosphere introduced otherwise **Permit-Required**

Confined Space Inventory-City of New London July 10, 2012

Space #	Location	Structure #	Type/Size	Access	Primary Hazard	Other	Entry Classification
New London Aquatic	Splash Pad Surge Tank	Photo(s) #8	Concrete	Top	Air Quality	Fall	**Permit-Required**
Memorial Park	Restroom Sump Pit	Photo(s) #9	Concrete access dirt floor	Top	Air Quality	Fall and Configuration	**Permit-Required**
Memorial Park	Concession Stand Sump Pit	Photo(s) #10	Plastic Cover	Top	Air Quality		**Alternate Entry-Continuous Monitoring and Ventilation Required**
Memorial Park	Exterior Restroom Pit	NO PHOTO	Manhole	Top	Air Quality	Configuration	**Permit-Required**
Pfeifer Park	Holding Tanks	Photo(s) #11	Concrete Covers	Top	Air Quality	Engulfment/Configuration	**Permit-Required**
Franklin Park	Bubbler Pit	Photo(s) #12	Manhole	Top	Air Quality	Fall	**Permit-Required**

Confined Space Inventory-City of New London July 10, 2012

Photo #1 Hatten Sanitary Stadium Holding Tank

Confined Space Inventory-City of New London July 10, 2012

Photo #2 Kunkle Building Sump Pump Pit

Confined Space Inventory-City of New London July 10, 2012

Photo #3 Kunkle Basement Pool Pit

Confined Space Inventory-City of New London July 10, 2012

Photo #4 New London Aquatic Chemical Room Pump pit

Confined Space Inventory-City of New London July 10, 2012

Photo #5 New London Aquatic Chemical Room Filter Pit

Photo #6 New London Aquatic Chemical Room Surge Tank

Confined Space Inventory-City of New London July 10, 2012

Photo #7 New London Aquatic Chemical Room Sump Pit

Confined Space Inventory-City of New London July 10, 2012

Photo #8 New London Aquatic Splash Pad Surge Tank

Confined Space Inventory-City of New London July 10, 2012

Photo #9 Memorial Park Restroom Sump Pit

Confined Space Inventory-City of New London July 10, 2012

Photo #10 Memorial Park Concession Stand Sump Pit

Confined Space Inventory-City of New London July 10, 2012

Photo #11 Pfeifer Park Holding Tanks

Confined Space Inventory-City of New London July 10, 2012

Photo #12 Franklin Park Bubbler Pit